



WIAP®

MEMV®



International staff training in machine construction

Introduction: The WIAP shouldered young and old professionals, which were new and some already decades in operation. This staff is often in practice, but it was missing you with the foundation and the theory. With a special training program of WIAP which is designed to train the production during that WIAP trains the people during an ongoing production trained. A cost-conscious project that increases the quality of skilled workers. Also trains the trainers WIAP which perform this task.

PICTURE REPORT A23 bottle of oil used for lubrication

Topic: Wrong oil
Created: "HP Widmer"

A mistake !

Some years bought in the company dining & Müller Slidingway in Switzerland. It was also bought rust inhibitor.

The day came when there was no more Guideway stock. For this rust inhibitor with almost the same Ettikete. But just almost only.

Rustproofing does not have good sliding properties. Still, it was used as Gleitbahnenöl.
How long?



1: Such oil level around in operation. In plastic cans and tin drums. The sheet metal barrels are rusted.



Figure 2: In all lubrication, the containers were emptied and cleaned. What was there found upstream, was very frightening. Dirt and oil in place, rust in the grease containers. If we knew how long? The rust protection has a poor sliding property. Regardless of the preventive maintenance, these containers should anschauen once every 2 years and clean the inside. How often in the middle of production often on the night shift, an alarm, no oil. And quickly fill a container and oil. Was the vessel but clean?



Figure 3: The rust protection in the lubrication reservoir instead Gleitbahnöl.

Intensive training with maintenance program has in the matter, the WIAP.

A23 Wrong oil

Create and determines everything from one source.

www.wiap.ch

End image Report "HP. Widmer "Nov. 11

Template:

Place:

Date:

Created: sw-jw-iw-hp Widmer
WIAP AG Lts SA
Industriestrasse 48L
CH-4657 Dulliken

Phone: ++ 41 62 752 42 60

Fax: ++ 41 62 752 48 61

wiap@widmers.info www.wiap.ch

International Training WIAP

www.wiapwidmers.info:

Title: Bottles slideway oil used in the machine tool. machine cleaner

Description: The machine twitched and shook the axis motion and were hardly bearable because it was used instead slide oil machine cleaner.

A mistake

Which could be provided by language differences. But etiquette not ok

Content ok! Such tasks are now in an operation for quality assurance.

keyword:

The machines twitched and shook the axis motion, cause instead of slide oil machine cleaner
By language differences was due cause.
WIAP trains skilled workers.