

Photo report V37:

Project WIAP KFKOK Vietnam,

Project start Nov. 2010.

Preparation of this report 11/15/2015 Photo
i / HP Widmer

Table of Contents:



P1: 1. From left, school teacher Vietnam T8,
2. from left our WIAP Instrukter A24,
3. from left our Instrukter our WIAP A04,
4. from left our WIAP Instrukter A15,
5. from left our WIAP Instrukter A08,
6th + 7th from left, our two apprentices D
7. 1-4 from right E apprentices



P2: Planning and dust removed, the next step.



P3: Left, the teacher of the school, the right
instrukter A8.



P4: Here we have seen during the tour that all
machines are very dirty. There we too little
cleaned.



P5: Very dirty dishes, No matter where we have
been seen.

Photo report V37 Vietnam trip 3 2015 i / HPW



P6: The frame for the WIAP Dm2 S CNC lathe is dirty in a corner!



P9: In room 2 the mechanical workshop, all the drawers were inside very dirty and messy.



P7: The small band saw that we brought to the last container No. 9. Very dirty.



P10: These clamps we wanted in the mail send to Switzerland. But the state is not at all nice. If so having arrived in Switzerland that would be one of the greatest disgraces for our school system.



P8: In painting, were certainly more than 100 cans without color! Why not disposed of?



P11: These large clamps have the visual inspection also failed. Spindle rusty not oiled! Deburring insufficient.

Photo report V37 Vietnam trip 3 2015 i / HPW



P12: The big heavy clamps clamp 400 mm.



P14: These were bands that we bought to bind. When the air in Vietnam they are disintegrated by the air not good.



P13: Now go the big clamps in the welding room 1 to rework. Re-welding and visually make improvements where the instructor is responsible A04.



P15: This wall we have 2 x repainted since 2011. Again after 2 years it looks as if they had never been painted 20 years. The thing we need to track.



P16: Our apprentices with the instructors. Too bad that the chef instructor as a model on all pictures wearing open sandals stands there, these are our role models!

Photo report V37 Vietnam trip 3 2015 i / HPW



P17: Here is the grinding which we got from the company. Flückiger, Gesenkschmiede Obernburg.



P20: Separating the target 1b of the castle. For some reason, the key has disappeared.




P18: The machine is attached to the bottom.



P21: The new wardrobes closet where all apprentices can put shoes. Teaching guidelines put away and can move in teaching. The cabinet made the apprentices.



P19: Our electrician teacher joins them.



P22: As the apprentices still have holes drilled that the glove compartment has a little air.

Photo report V37 Vietnam trip 3 2015 i / HPW



P23: The little hardening oven in the repair, the door was broken.



P26: A small tour on Saturday has given us more impressions of the island.



P24: and rusted. The heat has also been stone repositioned.



P27: front of our hotel window a man who works in the water.



P25: Because we went with the director Bang and our coordinator Le Tung Hieu on Friday evening to Sunday noon on the island of Phu Quoc to lead also planning discussions.



P28: On Sunday morning before departure to airport Phu Quoc our director Bang from the school where we have training rooms.



P29: Funny seats in the reception desk of the Hotel Chez Carole which is operated outdoors with only a roof.



P32: The has long been left standing machine WIAP DM25 we have now moved from the space 3a in the chamber 5, that we can have much more fine.



P30: On Monday morning was still opened the door of the school. We were the first since the allowed through.



P33: With a palett carriage on the very poor cement floor because so much holes, the transport was quite difficult. But we managed.



P31: In our school system, we have 2 weeks mainly just everything we reorganized something that apprentices have more joy.



P34: Also all drills were removed from the wooden pallets, since we have found a lot of bugs in the wooden pallets.

Photo report V37 Vietnam trip 3 2015 i / HPW



P35: We are glad that we made the mobile crane 2 tons.



P38: Thousands vermin were there in the shoes, we have thrown away everything. Also, all wooden boxes removed.



P36: In the room 3a we also have our tool finally nice. It was everything hung in a grid box.



P39: Dare stand in the assembly room looked terrible. Because have a lot Gekos her "Schitt" dumped it looked really pathetic. We wondered what was our apprentices and instructors in recent months made.



P37: Were still shoes behind my desk. Unfortunately, probably long no longer cleaned.



P40: Almost no tools in it, Geko "filth" and what else there was rusted.

Photo report V37 Vietnam trip 3 2015 i / HPW



P41: Pallets were much greedy down from vermin.



P44: For the remaining goods was also a truck and took it off. In Vietnam that is free of charge.



P42: As you can see this "Term Itten tracks". Bad.



P45: In the room 4a we have the cutting room. On all machines we made the yellow boxes. That this saw is 2 yellow boxes has, shows that where the second mount was too lazy to walk to the machine and did not see that even a yellow box is mounted. The documents in the yellow boxes are not filled well that we now tested with inspections.



P43: We have to dispose asked the pallets into the open air. These were picked up in minutes and warn disappeared. We wanted to burn but came not to do so. Min. 20 pallets and 15 yards, we have thrown away.



Photo report V37 Vietnam trip 3 2015 i / HPW

P46: We have several times taken together on this stay all apprentices with the instructors and made a tour of the 9 training rooms around 1000m / 2. She had to write down everything to make your own list of open issues.



P47: We have reviewed the material storage in room 1 of the welding shop and determined the actions of the order.



P48: We have 10 laptops at school. Now had all apprentices himself the pending list write to Excel in a way that we can translate it in Goggle.



P49: On the penultimate evening we all instructors and all apprentices for dinner they invited were very happy.



P50: A day before our departure, we then brought 4 clamps to the post, 2 cables and a spirit level. Total ca 45 Kg. Costs 168 CHF with sea freight. We've asked for months. Unfortunately, it has never worked.



P51: 3 such transport documents were there.

Photo report V37 Vietnam trip 3 2015 i / HPW



P52: On Friday morning was still the great Teacher's Day in Vietnam of the 20 of November. Here left the headmaster Bang and next to him the former retired Director.



P55: Our apprentices from the D group is the selected group spokesman of our WIAP project.



P53: There was now even a group picture of the whole school by all teachers.



P56: After the ceremony, still came to enjoy the meal together with all our instructors and the school management.



P54: Rear other wall nor the picture of Karl Marx and Lenin. The people, that played a very important role in communism.



P57: On shot the celebration it was very interesting under our table was not an object among all the other tables were large quantities of waste everything under the table. Rear can see there after the tables were already cleared.

Photo report V37 Vietnam trip 3 2015 i / HPW

Final comment. We have made the trip because we really wanted to perform the ceremony of the C group yet. As we have seen the school system since we were shocked. Everything extremely dirty unkempt most rooms were almost no longer enter. That is why we said the first is cleared, order and then we'll see.

Even objects were no longer there and the main instructors have demonstrated every day without protective footwear in that they have no role models.

We will now hold again our guidelines and who does not want to comply we no longer want in the school system. Order and discipline will now be P1.

End Photo Report V37 HPW / iw 11/21/2015